103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре		Make
CC0222	11m x 1.6m x 0.3m		Water slide		Castle capers
Name and address of owr	ner	Boing			
Manufacture date		Place of inspection			Name of inspector
2018		Boing			Louise Reade

Anchorage	Structure	Totally enclosed
How Many/type	Seams & stitching	Exits
Accessories	Blower length	Exit markings
Blower	Inside wall height	Independent support
Inlet, outlet mesh	Fall off height	Deflation
Cable and socket	Step/ramp	Emergency lighting
Impeller & flap	Entrapment	Slides
1.5hp	Trough depth	Platform height
PAT test	Grounding	Platform wall
Material	Sharp angles	1 st M wall
Fabric FR/strength	Stability	Slope remainder
Zips	Pressure	Climb
Thread	deflation	Run out
Rope	Air loss	End
Netting	Markings	Slip sheet
Windows	Identifications	Climb sheet
Artwork	Walls & towers	Run out length

<u>below</u>

How many users to height

1 M = 1	1.2 M = 1	1.5 M = 1	1.8 M = 1

Risk assessment	Notes	
This inflatable is a safety bed on which the designated activity	Max height = 1.8m	
only should take place (No bouncing or play should take place at	Max users at this height = 1	
any time) Designated entrance and exit areas should be adhered		
to at all times. This safety certificate is for the inflatable only.		
FULL ADULT SUPERVISION AT ALL TIMES		

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 28.05.24

Contre Reade Allogs Finite Analysis Rained Inspector Micratante 2024

Expiry date: 28.05.25