103 The Street, Adisham, Canterbury, Kent, CT33JP, England.

07568487894

 $castle capers_bouncy castle repairs@yahoo.com$

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре	Make	
CC0634	6m x 6m x 1.7m		Track	Unknown	
Name and address of owner		Boing			
Manufacture date		Place of inspection		Name of inspector	
Unknown		Boing		Louise Reade	

Anchorage	Structure	Totally enclosed
How Many/type	Seams & stitching	Exits
Accessories	Blower length	Exit markings
Blower	Inside wall height	Independent support
Inlet, outlet mesh	Fall off height	Deflation
Cable and socket	Step/ramp	Emergency lighting
Impeller & flap	Entrapment	Slides
1.5hp	Trough depth	Platform height
PAT test	Grounding	Platform wall
Material	Sharp angles	1 st M wall
Fabric FR/strength	Stability	Slope remainder
Zips	Pressure	Climb
Thread	deflation	Run out
Rope	Air loss	End
Netting	Markings	Slip sheet
Windows	Identifications	Climb sheet
Artwork	Walls & towers	Run out length

All parts relevant to this unit have been inspected and found satisfactory unless listed below

How many users to height

1 M = 12 1.5 M = 12 1.5 M = 12 1.8 M = 12	
---	--

Risk assessment	Notes
This inflatable is a safety bed on which the designated activity	Max height = 1.8m
only should take place (No bouncing or play should take place at	Max users at this height = 12
any time) Designated entrance and exit areas should be adhered	
to at all times. This safety certificate is for the inflatable only.	
FULL ADULT SUPERVISION AT ALL TIMES	

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 28.05.24

Expiry date: 28.05.25

